

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

## OLENE S. WALKER Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

## **Inspection Report**

Permit Number:	C0150015
Inspection Type:	TECHNICAL
Inspection Date:	Thursday, April 01, 2004
Start Date/Time:	04/01/2004 2:00:00 PM
End Date/Time:	04/01/2004 3:00:00 PM
Last Inspection:	Monday, March 29, 2004

Inspector: <u>Priscilla Burton, Environmental Scientist III</u>
Weather: <u>overcast, thunder, lightening, very light rain</u>

InspectionID Report Number: 225

Accepted by: dhaddock 04/05/2004

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO SESSER OPERATIONS

Site: EMERY DEEP MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages		Mineral Ownership	Types of Operations	
5,180.00	<b>Total Permitted</b>	☐ Federal	✓ Underground	
247.00	<b>Total Disturbed</b>	☐ State	Surface	
	Phase I	☐ County	Loadout	
	Phase II	☐ Fee	Processing	
	Phase III	☐ Other	Reprocessing	

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Observed the addition of recently salvaged soil to the topsoil pile and watered the cryptogams transplanted to the pile on 3/18/04.

Inspector's Signature:	Date	Monday, April 05, 2004

Priscilla Burton, Environmental Scientist III

Inspector ID Number: 37

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining



Permit Number: C0150015
Inspection Type: TECHNICAL

Inspection Date: Thursday, April 01, 2004 Page 2 of 3

## REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil			✓	
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	b Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150015
Inspection Type: TECHNICAL

Inspection Date: Thursday, April 01, 2004

Page 3 of 3

## 3. Topsoil

Topsoil was salvaged from the 0.5 acre addition east of the existing fence on March 24 through March 26, 2004. Mr. Patrick Collins was on site to guide the soil salvage on March 24. Both he and Mr. Steve Behling of Consol indicated that there was about double the volume anticipated salvaged from the site with pockets of Persayo soils that were four feet deep. An as built volume of the additional soil salvaged and stored in the stockpile will be forthcoming and is estimated to be between 2,500 and 3,400 CY. (The expectation was to salvage 1,400 CY). The soil has been added to the west and north sides of the pile. The berms were reshaped. The top of the pile has been gouged, but not the sides of the pile. The Permittee should gouge the sides of the pile before seeding. The pile has not yet been seeded or mulched. The seed mix described in the MRP for the pile is the native seed mix described on page 20 of Chapter VIII and includes blue grama, thickspike wheat, alkali sacaton, winterfat, fourwing saltbush, globe mallow, and shadscale. Water was applied to the transplanted cryptogams on the stockpile using the backpack sprayer. Approxmately 2 gallons of water was used on the 20 transplants.